## **EAST Search History**

## EAST Search History (Prior Art)

< This search history is empty>

## EAST Search History (Interference)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	0	(top sealing plate battery filter cap valve convex flange bend caulked contact stronger).clm.	US- PGPUB; UPAD	AND	ON	2010/10/04 15:53
L2	···O	(top plate battery filter cap valve convex flange bend contact stronger).clm.	US- PGPUB; UPAD	AND	ON	2010/10/04 15:54
L3	O	(top plate filter cap valve convex flange bend contact stronger).clm.	US- PGPUB; UPAD	AND	MON Manus	2010/10/04 15:54
L4	0	(top plate filter cap valve convex flange bend contact).clm.	US- PGPUB; UPAD	AND	ON	2010/10/04 15:54
L5	0	(top plate filter cap valve convex flange bend). clm.	US- PGPUB; UPAD	AND	ON	2010/10/04 15:54

L6	0	(top plate filter cap valve convex flange).clm.	US- PGPUB; UPAD	AND	ON	2010/10/04 15:54
L7	0	(plate filter cap valve convex flange).clm.	US- PGPUB; UPAD	AND	ON	2010/10/04 15:54
L8	28	(plate filter cap valve flange).clm.	US- PGPUB; UPAD	AND	ON	2010/10/04 15:54
L9	0	(plate filter cap valve battery flange).clm.	US- PGPUB; UPAD	AND	ON	2010/10/04 15:54

10/4/2010 3:55:21 PM C:\ Documents and Settings\ rhodge\ My Documents\ EAST\ Workspaces \ 09980880 Battery Sealing Plate.wsp